

Date : 05/14/2026
Project No : 2026C101
Client Company : Artisan
Arrival Time : 05/14/2026 08:00
Onsite Hours : 02:00

ASEC Report ID : 94345
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots
Project Location : Dallas
Weather : Sunny
Departure Time : 05/14/2026 10:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site as requested by the contractor for the observation/testing of the placement of fill/backfill. DCP testing was performed on for NW U3 PH 5A-3 DCP's at Rosemary Landing, specifically, Lots #1173, #1174, and #1083 located on Rosemary Landing. Each lot was tested in the front of the lot and back of the lot. The lots appear to meet job specifications for soil bearing pressures and appear compacted as per job specifications. A copy of the test results will be provided in the pictures below.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 05/14/2026
Project No : 2026C101
Client Company : Artisan
Arrival Time : 05/14/2026 08:00
Onsite Hours : 02:00

ASEC Report ID : 94345
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots
Project Location : Dallas
Weather : Sunny
Departure Time : 05/14/2026 10:00
ASEC Technician Name : Sean Willett



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.