

Date : 06/22/2026  
Project No : 2026C101  
Client Company : Artisan  
Arrival Time : 06/22/2026 07:30  
Onsite Hours : 9:00

ASEC Report ID : 95448  
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 06/22/2026 16:30  
ASEC Technician Name : Clyde Smith


As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

On the above date our representative was on site to observe the contractor performed subbase and subgrade preparation for the deceleration lane and turn in entrance lane. The contractor clipped the subgrade at the entrance lane an additional -6" as recommended, removing saturated in-place soils. The clipped area was replaced with additional base stone. The contractor also appeared to cut a power line going to the light pole that wasn't repaired. It was recommended to add water to the subbase stone added today.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Sub grade clipped -6" at entrance drive




Sub grade probed to determine -6" clip

Date : 06/22/2026  
Project No : 2026C101  
Client Company : Artisan  
Arrival Time : 06/22/2026 07:30  
Onsite Hours : 9:00

ASEC Report ID : 95448  
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 06/22/2026 16:30  
ASEC Technician Name : Clyde Smith



Sub base prep. at deceleration lane



Date : 06/22/2026  
Project No : 2026C101  
Client Company : Artisan  
Arrival Time : 06/22/2026 07:30  
Onsite Hours : 9:00

ASEC Report ID : 95448  
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots  
Project Location : Dallas  
Weather : cloudy  
Departure Time : 06/22/2026 16:30  
ASEC Technician Name : Clyde Smith



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.