Concrete Test Report

Date : 03/23/2026
Project No : 2026C115-WO 1
Client Company : WSP
Arrival Time :
Onsite Hours : N/A

ASEC Report ID : 91975
Name of the Project : Lanier Islands Parkway
Project Location : Buford
Weather : N/A
Departure Time :
ASEC Technician Name : Balu Mylabathula

Location(S): F2, F8, F16, F20

Testing: 1 Set of concrete specimens (5 per set) were cast during the cast-in-place concrete pour at the above referenced location, in accordance with ASTM C31. The specimen will remain on site for the initial 24-48 hrs curing.

Compliance: ☒Field placement of concrete appeared to be in general accordance with the project specifications (i.e., slump, temperature, etc) (refer to remarks below)
☐Deviations and/or noncompliances were noted during the field placement (refer to remarks below)

Specimen Pick Up: 1 Sets of concrete specimens/ 5 specimen per set were picked up & transported to AS Engineering and Consulting LLC (ASEC) for curing and testing in accordance with ASTM C39, C670/1231

Field Curing: Specimen were stored for the initial 24 hours
☒ Near the poured structure
☐ In an insulated curing box
☐ Other

Remarks:

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consultiing LLC.

AS Engineering and Consulting LLC

Concrete Test Report

Date : 03/23/2026
Project No : 2026C115-WO 1
Client Company : WSP
Arrival Time :
Onsite Hours : N/A

ASEC Report ID : 91975
Name of the Project : Lanier Islands Parkway
Project Location : Buford
Weather : N/A
Departure Time :
ASEC Technician Name : Balu Mylabathula

PLACEMENT INFORMATION – Cylinder

Set Number: A
Date Sampled: 03/23/2026
Sampled By: Balu Mylabathula
Contractor: CONLAN COMPANY
Truck Number: 1
Time Batched: N/A
Location of Placement: F2
Number of Samples Cast: 5
Ambient Temp (°f): N/A
Slump (in.): 6

Laboratory Number: 2026-067
Time Sampled: 04:00
Concrete Supplier: MORGAN
Mix ID: 4000 57-89 SOG NA
Quantity of Load: 10
Specified Strength: 4000
Concrete Temp (°f): 70
Air Content (%): 3
Unit Weight (pcf): 148.8
Water Added (gal.): N/A

Specimen Number	Scheduled Test Date	Date Tested	Age (Days)	Dia (in.)	Area (sq in.)	Max Load (lbf)	Strength (psi)	% Design Strength	Fracture Type
1	03/30/2026	03/30/2026	7	4.00	12.57	51338	4080	102.0	Type 2
2	04/20/2026	04/20/2026	28	3.98	12.41	64695	5210	130.3	Type 3
3	04/20/2026	04/20/2026	28	3.98	12.41	67209	5420	135.5	Type 2
4	04/20/2026	04/20/2026	28	3.98	12.41	64880	5230	130.8	Type 3
5	05/18/2026	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

UNLESS OTHERWISE SPECIFIED, TESTS WERE PERFORMED IN ACCORDANCE WITH ASTM METHODS C31, C39, C138, C143, C173, C1064.

(1) Cone (2) Cone-split (3) Vertical (4) Shear (5) Edge Fracture (6) Pointed

Catherine Lanier
Lab Manager

Kenneth Mosman

AS Engineering and Consulting LLC

Concrete Test Report

Date : 03/23/2026
Project No : 2026C115-WO 1
Client Company : WSP
Arrival Time :
Onsite Hours : N/A

ASEC Report ID : 91975
Name of the Project : Lanier Islands Parkway
Project Location : Buford
Weather : N/A
Departure Time :
ASEC Technician Name : Balu Mylabathula

PLACEMENT INFORMATION – Cylinder

Set Number:	B	**Laboratory Number:**	2026-067
Date Sampled:	03/23/2026	**Time Sampled:**	5
Sampled By:	Balu Mylabathula	**Concrete Supplier:**	MORGAN
Contractor:	COLMAN	**Mix ID:**	4000 57-89 SOG NA
Truck Number:	11	**Quantity of Load:**	10
Time Batched:	N/A	**Specified Strength:**	4000
Location of Placement:	F8	**Concrete Temp (°f):**	75
Number of Samples Cast:	5	**Air Content (%):**	2.5
Ambient Temp (°f):	N/A	**Unit Weight (pcf):**	147.5
Slump (in.):	6	**Water Added (gal.):**	N/A

Specimen Number	Scheduled Test Date	Date Tested	Age (Days)	Dia (in.)	Area (sq in.)	Max Load (lbf)	Strength (psi)	% Design Strength	Fracture Type
No test results available									

UNLESS OTHERWISE SPECIFIED, TESTS WERE PERFORMED IN ACCORDANCE WITH ASTM METHODS C31, C39, C138, C143, C173, C1064.

(1) Cone (2) Cone-split (3) Vertical (4) Shear (5) Edge Fracture (6) Pointed

Catherine Lanier
l
Lab Manager

Kenneth Mosman

AS Engineering and Consulting LLC

Concrete Test Report

Date : 03/23/2026
Project No : 2026C115-WO 1
Client Company : WSP
Arrival Time :
Onsite Hours : N/A

ASEC Report ID : 91975
Name of the Project : Lanier Islands Parkway
Project Location : Buford
Weather : N/A
Departure Time :
ASEC Technician Name : Balu Mylabathula

PLACEMENT INFORMATION – Cylinder

Set Number:	C	**Laboratory Number:**	2026-067
Date Sampled:	03/23/2026	**Time Sampled:**	6
Sampled By:	Balu Mylabathula	**Concrete Supplier:**	MORGAN
Contractor:	COLMAN	**Mix ID:**	4000 57-89 SOG NA
Truck Number:	21	**Quantity of Load:**	10
Time Batched:	N/A	**Specified Strength:**	4000
Location of Placement:	F16	**Concrete Temp (°f):**	70
Number of Samples Cast:	5	**Air Content (%):**	3
Ambient Temp (°f):	N/A	**Unit Weight (pcf):**	149.7
Slump (in.):	5	**Water Added (gal.):**	N/A

Specimen Number	Scheduled Test Date	Date Tested	Age (Days)	Dia (in.)	Area (sq in.)	Max Load (lbf)	Strength (psi)	% Design Strength	Fracture Type
No test results available									

UNLESS OTHERWISE SPECIFIED, TESTS WERE PERFORMED IN ACCORDANCE WITH ASTM METHODS C31, C39, C138, C143, C173, C1064.

(1) Cone (2) Cone-split (3) Vertical (4) Shear (5) Edge Fracture (6) Pointed

Catherine Lanier

Catherine Lanier
l
Lab Manager

Kenneth Mosman

Kenneth Mosman

AS Engineering and Consulting LLC

Concrete Test Report

Date : 03/23/2026
Project No : 2026C115-WO 1
Client Company : WSP
Arrival Time :
Onsite Hours : N/A

ASEC Report ID : 91975
Name of the Project : Lanier Islands Parkway
Project Location : Buford
Weather : N/A
Departure Time :
ASEC Technician Name : Balu Mylabathula

PLACEMENT INFORMATION – Cylinder

Set Number:	D	**Laboratory Number:**	2026-067
Date Sampled:	03/23/2026	**Time Sampled:**	7
Sampled By:	Balu Mylabathula	**Concrete Supplier:**	MORGAN
Contractor:	COLMAN	**Mix ID:**	4000 57-89 SOG NA
Truck Number:	31	**Quantity of Load:**	10
Time Batched:	N/A	**Specified Strength:**	4000
Location of Placement:	F20	**Concrete Temp (°f):**	70
Number of Samples Cast:	5	**Air Content (%):**	2.5
Ambient Temp (°f):	N/A	**Unit Weight (pcf):**	147.6
Slump (in.):	5	**Water Added (gal.):**	N/A

Specimen Number	Scheduled Test Date	Date Tested	Age (Days)	Dia (in.)	Area (sq in.)	Max Load (lbf)	Strength (psi)	% Design Strength	Fracture Type
No test results available									

UNLESS OTHERWISE SPECIFIED, TESTS WERE PERFORMED IN ACCORDANCE WITH ASTM METHODS C31, C39, C138, C143, C173, C1064.

(1) Cone (2) Cone-split (3) Vertical (4) Shear (5) Edge Fracture (6) Pointed

Catherine Lanier

Catherine Lanier
l
Lab Manager

Kenneth Mosman

Kenneth Mosman