

Date : 05/12/2026
Project No : 2026C125
Client Company : Lewis Contracting
Arrival Time : 05/12/2026 12:00
Onsite Hours : 04:00

ASEC Report ID : 94367
Name of the Project : Pittman Park - Garibaldi St. Stormwater
Project Location : Atlanta
Weather : sunny
Departure Time : 05/12/2026 16:00
ASEC Technician Name : Samara Simha Reddy Kandi

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
05/12/2026	1	18.8	99.9	Proctor 1	104.9	19.8	95.2	95	D6938	Pass
Location : Approximately 25 feet from manhole F1, Elv/Depth :6 inches below finished grade										
Comment :										
Tested By : Samara Simha Reddy Kandi Gauge Serial No. : 38069										
05/12/2026	2	16.8	117.2	Proctor 1	104.9	19.8	95.6	95	D6938	Pass
Location : Approximately 50 feet from manhole F1, Elv/Depth :6 inches below finished grade										
Comment :										
Tested By : Samara Simha Reddy Kandi Gauge Serial No. : 38069										

Remark: Test performed in general accordance with signed referenced ASTM Method.

Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 05/12/2026
Project No : 2026C125
Client Company : Lewis Contracting
Arrival Time : 05/12/2026 12:00
Onsite Hours : 04:00

ASEC Report ID : 94367
Name of the Project : Pittman Park - Garibaldi St. Stormwater
Project Location : Atlanta
Weather : sunny
Departure Time : 05/12/2026 16:00
ASEC Technician Name : Samara Simha Reddy Kandi

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
03/28/2026	Proctor 1	104.9	19.8	Standard	Red, brown sandy SILT with some clay and GAB