

Density Test Report

Date : 11/05/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 11/05/2020 10:00
Onsite Hours : 06:00

ASEC Report ID : 1314
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 11/05/2020 16:00
ASEC Technician Name : Ramchandra Mogulla

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
11/05/2020	8	19.8	92.5	P-2	102.3	18.0	90.4	90	D2937	Pass
Location : Lot # 9, Elv/Depth :-8 feet Comment : Tested By : Ramchandra Mogulla										
11/05/2020	9	15.4	98.7	P-2	102.3	18.0	96.5	90	D2937	Pass
Location : Lot # 9 , Elv/Depth :-7 Feet Comment : Tested By : Ramchandra Mogulla										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Density Test Report

Date : 11/05/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 11/05/2020 10:00
Onsite Hours : 06:00

ASEC Report ID : 1314
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 11/05/2020 16:00
ASEC Technician Name : Ramchandra Mogulla

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
10/23/2020	P-1	97.4	21	Standard	Red Brown micaceous Silty SAND (SM)
11/03/2020	P-2	102.3	18.0	Standard	Brown micaceous Silty SAND (SM)