

Date : 12/08/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 12/08/2020 10:00
Onsite Hours : 05:00

ASEC Report ID : 1439
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 12/08/2020 15:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today.

- a. Work continued along the road way for the Sewer Line A. The asphalt along the roadway was saw cut from the intersection of River rd and Green Pastures Way to Cannon Walk and River Rd for and were within the plan specifications.
- b. No structural fill was placed today.



Green Pastures / River Rd Intersection



Saw Cut following Civil Plans



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.