



Date : 04/26/2021
Project No : 2020C002
Client Company : Toll Bros. Inc.
Arrival Time : 04/26/2021 08:00
Onsite Hours : 07:00

ASEC Report ID : 14601
Name of the Project : Northfields at Polo Fields
Project Location : 4805 Pittman Road, Forsyth County, Georgia
Weather : Cloudy
Departure Time : 04/26/2021 15:00
ASEC Technician Name : Andrew McCullough

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were made on site today.

1. The onsite inspector met with the site superintendent Morris Pucket and the project engineer Ram Mogulla, to walk the site in the area of lot #27 in regards to the stabilization efforts from the previous day. Test pits were dug inside of lot #27 and the adjacent road to quantify the amount and type of remediation required in this area. Please refer to Ram Mogulla report/recommendation for a complete list of findings.
2. Following the walk through, the inspector and the site superintendent walked the previously excavated area around lot #27 and quantified a total linear footage of heavy organic material removed from this area. Please refer to the attached document for a map of the area with total measurements.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.