

Density Test Report

Date : 12/10/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 12/10/2020 09:00
Onsite Hours : 06:00

ASEC Report ID : 1479
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 12/10/2020 15:00
ASEC Technician Name : Dave Bek

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
12/10/2020	1	16.3	98.9	P-1	97.4	21	101.5	98	D2937	Pass
Location : Sewer Line A, Elv/Depth :3 Feet Below FF										
Comment :										
Tested By : Dave Bek										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Density Test Report

Date : 12/10/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 12/10/2020 09:00
Onsite Hours : 06:00

ASEC Report ID : 1479
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 12/10/2020 15:00
ASEC Technician Name : Dave Bek

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
10/23/2020	P-1	97.4	21	Standard	Red Brown micaceous Silty SAND (SM)
11/03/2020	P-2	102.3	18.0	Standard	Brown micaceous Silty SAND (SM)