


Date : 12/21/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 12/21/2020 09:00
Onsite Hours : 06:00

ASEC Report ID : 1509
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 12/21/2020 15:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

1. Work was continued on the Storm drain line A.
2. No structural fill was placed today.



Date : 12/21/2020
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 12/21/2020 09:00
Onsite Hours : 06:00

Daily Field Report

ASEC Report ID : 1509
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Sunny
Departure Time : 12/21/2020 15:00
ASEC Technician Name : Dave Bek



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla

**GA P.E. 036021
Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.