

Date : 01/06/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 01/06/2021 11:00
Onsite Hours : 02:00

ASEC Report ID : 1534
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Cloudy
Departure Time : 01/06/2021 13:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and

materials submittals. The following observations were made on site today:

On-site today @ 11:00am today to perform DCP tests on footings for residential unit at 6168 Collins Road, Acworth, GA. The test results of the DCP show that the current compaction is within plan specifications (see DCP test results). The rebar for the slab and footing was being installed and was found to be in general accordance with project specifications.



Date : 01/06/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 01/06/2021 11:00
Onsite Hours : 02:00

ASEC Report ID : 1534
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Cloudy
Departure Time : 01/06/2021 13:00
ASEC Technician Name : Dave Bek



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla

GA P.E. 036021

Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.