

Date : 01/20/2021  
Project No : 2020C009  
Client Company : DR Horton  
Arrival Time : 01/20/2021 11:00  
Onsite Hours : 04:00

ASEC Report ID : 1562  
Name of the Project : Monet Gardens  
Project Location : River Road at Green Pastures Way,  
Ellenwood, GA  
Weather : Cloudy  
Departure Time : 01/20/2021 15:00  
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

- Work continued on Wall 1 (West of lot 9)
  - Rip rap was placed by Dekalb Pipeline to remediate the drainage of the detention pond outlet.
  - The contractor installed 34 stone wrapped in separation fabric to the section of Wall 1 from 0' - 55'
- Grading continued on lots 10 - 19



Drainage Remediation Retention Pond Outlet



57 Stone wrapped in separation fabric - Retaining wall foundation



Grading lot 10 - 19

## Daily Field Report

Date : 01/20/2021  
Project No : 2020C009  
Client Company : DR Horton  
Arrival Time : 01/20/2021 11:00  
Onsite Hours : 04:00

ASEC Report ID : 1562  
Name of the Project : Monet Gardens  
Project Location : River Road at Green Pastures Way,  
Ellenwood, GA  
Weather : Cloudy  
Departure Time : 01/20/2021 15:00  
ASEC Technician Name : Dave Bek



**Dave Bek**

---

**Senior Engineering Technician**



**Ramchandra R. Mogulla**

**GA P.E. 036021  
Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.