

Date : 02/23/2021
Project No : 2020C002
Client Company : Toll Bros. Inc.
Arrival Time : 02/23/2021 08:00
Onsite Hours : 07:00

ASEC Report ID : 1728
Name of the Project : Northfields at Polo Fields
Project Location : 4805 Pittman Road, Forsyth County, Georgia
Weather : Sunny
Departure Time : 02/23/2021 15:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today

1. Lots 33 - 36 had been staked and prepped for two temporary retention ponds.(SD4-1, SD4-3) Top soil had been previously cut from the surface (depth of approximately 2 feet) to the usable soil below.
2. A moisture taken of a soil sample from lot 35 and was found to be at 25% (lot 36 - 35)
3. Completely saturated areas along the silt fence for lots 34 - 33 showed signs of "pumping" from general foot traffic, and also areas of water retention (shallow pools of water)
4. A 5 lb bucket of soil was taken to wood engineering for standard compaction tests. The soil was a Red/Yellow Silty Sand material located 1 foot below the surface of Lot 34. The sample was taken from an area that was cut using a full size bulldozer.



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.