

Date : 02/25/2021  
Project No : 2020C009  
Client Company : DR Horton  
Arrival Time : 02/25/2021 11:00  
Onsite Hours : 05:00

ASEC Report ID : 1739  
Name of the Project : Monet Gardens  
Project Location : River Road at Green Pastures Way,  
Ellenwood, GA  
Weather : Sunny  
Departure Time : 02/25/2021 16:00  
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today

DCP tests were performed on completed lot(s) 6 - 13 (see DCP report) based on the DCP test results the compaction was within plan specifications.



**Dave Bek**

---

**Senior Engineering Technician**



**Ramchandra R. Mogulla**  
**GA P.E. 036021**  
**Senior Engineer**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.