

Date : 03/01/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 03/01/2021 08:00
Onsite Hours : 02:00

ASEC Report ID : 1776
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : Rainy Overcast
Departure Time : 03/01/2021 10:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

A rebar and footing inspection was scheduled for the subject property 6172 Collins Rd, Acworth GA 30101 (Lot 5)

- Based on the rebar size (#4), placement (single row spaced at 6 inches apart) with 2" chairs. The rebar placement was consistent, acceptable and within plan specifications.
- Two DCP tests were performed (see DCP test results) Based on the density test results, visual observation and random probing, the footings was found to be acceptable and within plan specifications.



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.