

Date : 03/01/2021
Project No : 2020C009
Client Company : DR Horton
Arrival Time : 03/01/2021 11:00
Onsite Hours : 04:00

ASEC Report ID : 1800
Name of the Project : Monet Gardens
Project Location : River Road at Green Pastures Way,
Ellenwood, GA
Weather : Overcast / Rainy
Departure Time : 03/01/2021 15:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today.

DCP tests were performed on completed lot(s) 5 - 1 (see DCP report) based on the DCP test results, visual observation and general probing the compaction was within plan specifications.



Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.