

Date : 06/04/2021
Project No : 2020C002
Client Company : Toll Bros. Inc.
Arrival Time : 06/04/2021 10:00
Onsite Hours : 06:00

ASEC Report ID : 20462
Name of the Project : Northfields at Polo Fields
Project Location : 4805 Pittman Road, Forsyth County, Georgia
Weather : Overcast
Departure Time : 06/04/2021 16:00
ASEC Technician Name : Dave Bek

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today

Upon arrival to the site the writer observed the following:

At the secondary entrance (off Pittman rd), there was a transfer pit excavation (along the slope lot 5, approximately 17ft deep by 40 ft wide.) located exclusively in the slope area. The contractor explained that the good soil material was removed and unusable soil would be returned to that area.

Work began on the soil bridge over creek 2. The writer observed the contractor initially draining the existing water, which was then followed by the removal of the top layer of highly organic material and sediment build up, followed by the addition of 2 feet of bridge lift and a final compacted layer.

Excavation and placement for the sewer pipe was also underway from MHBA70 to MHBA80.



Transfer Pit



Sewer Line Excavation

Date : 06/04/2021
Project No : 2020C002
Client Company : Toll Bros. Inc.
Arrival Time : 06/04/2021 10:00
Onsite Hours : 06:00

ASEC Report ID : 20462
Name of the Project : Northfields at Polo Fields
Project Location : 4805 Pittman Road, Forsyth County, Georgia
Weather : Overcast
Departure Time : 06/04/2021 16:00
ASEC Technician Name : Dave Bek



Excavation creek 2



Soil Bridge uncompact fill placement



Compaction of soil bridge lift

A handwritten signature in blue ink, appearing to read "Dave Bek".

Dave Bek

Senior Engineering Technician



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.