

Date : 07/07/2021
Project No : 2021C058
Client Company : Pulte Group
Arrival Time :
Onsite Hours :

Daily Field Report

ASEC Report ID : 27665
Name of the Project : Parkside at Mason Mill
Project Location : Decatur, GA
Weather : sunny
Departure Time :
ASEC Technician Name :

As requested, a ASEC technician was present at the above referenced site for the purpose of conducting a basement wall inspection for lot #217

The wall evaluation was inspected visually for rebar type, spacing, lap distance, cleanliness, ect

The wall preparations appear to be in accordance with Southeast Zone, Date 12/08/2015, Carver & Eddington, NPC plan Number 2468.238-2468.237, Pulti Structural Drawling

by visual inspection, and is ready for concrete placement.

The superintendent has been notified of these findings.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.