

Date : 07/27/2021
Project No : 2021C070
Client Company : CCG Constructors LLC (Century)
Arrival Time : 07/27/2021 10:15
Onsite Hours : 00:30

ASEC Report ID : 31569
Name of the Project : Harmony Heights
Project Location : Mt. Olive Road at Brentwood Drive,
Commerce, GA
Weather : sunny
Departure Time : 07/27/2021 10:45
ASEC Technician Name : Russell Hendrix

As requested, the site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals. The following tests were performed onsite this day.

It was noted that upon visiting this site the project was continuing forward with removal of trees and further building of temporary detention ponds. It is anticipated that soil samples will be taken July 30th. This will be coordinated with grading foreman Mr. Victor Hugo.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.