

Date : 07/29/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 07/29/2021 09:00
Onsite Hours : 00:15

ASEC Report ID : 31889
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : sunny
Departure Time : 07/29/2021 09:15
ASEC Technician Name : Russell Hendrix

As requested, the site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawing/specifications, applicable codes, and materials submittals.

A request for a slab inspection was received and executed the morning of July 29th. Upon arrival the footing was incomplete. No inspection was conducted. Upon speaking with the Foreman for the slab contractor he requested I return the morning of July 30.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.