

Date : 07/30/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 07/30/2021 07:45
Onsite Hours : 02:15

ASEC Report ID : 32058
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : sunny
Departure Time : 07/30/2021 10:00
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today.

Upon arriving at Lot #28 the slab crew was finishing the installation of rebar and saddles. As per request of client a DCP test was conducted in front area of footing and another in the back of lot also in footing. Please find the attached test data.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.