

Date : 07/30/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 07/30/2021 07:00
Onsite Hours : 02:00

ASEC Report ID : 33531
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 07/30/2021 09:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

The contractor continued moving top soil from accumulated piles on site to be staged for use in fill slopes during later grading.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.