


Date : 08/11/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 08/11/2021 07:30
Onsite Hours : 03:30

ASEC Report ID : 33576
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 08/11/2021 11:00
ASEC Technician Name : Christopher Burrow II

As requested, an ASEC technician was present on the above mentioned job site. Moving dirt continued to form ramps up to boulders for the drill rig to access for drilling and blasting. Continued to move rock into place in fill areas.

Attached photo is the drill log for the above listed date as given by drill operator.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.