

Date : 09/20/2021
Project No : 2021C070
Client Company : CCG Constructors LLC (Century)
Arrival Time : 09/02/2021 12:00
Onsite Hours : 04:00

ASEC Report ID : 33878
Name of the Project : Harmony Heights
Project Location : Mt. Olive Road at Brentwood Drive,
Commerce, GA
Weather : sunny
Departure Time : 09/02/2021 16:00
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals.

Upon arrival at the project site a meeting was held with ALGC grading foreman Mr. Hugo Guerrero. We discussed the issue of excavated soil that would be an unusable type of material. This soil which filled 8 dump trucks would be transported to another location offsite while new soil would be used to replace the soil in question. Mr. Guerrero stated that a change order would be completed for the additional work.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.