

Date : 10/12/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 10/12/2021 10:30
Onsite Hours : 01:00

ASEC Report ID : 34289
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 10/12/2021 11:30
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

- Excavation and backfill of drain from culdesac to retention pond.
- Drilling on site performed by Precision Blasting.
- Rock breaking continued on site.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.