

Date : 10/14/2021
Project No : 2021G090
Client Company : DR Horton
Arrival Time : 10/14/2021 14:00
Onsite Hours : 01:00

ASEC Report ID : 34309
Name of the Project : Brooks Road Tract
Project Location : 1611 Brooks Road, Dacula, Georgia
Weather : Partly cloudy
Departure Time : 10/14/2021 15:00
ASEC Technician Name : Christopher Burrow II

The above mentioned ASEC technician was present at the wolf creek site for the purpose of a rebar inspection for Lot #106. After visual inspection the rebar was found to be within job specifications for size, spacing and quantity. The contractor was notified of these results.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.