

Date : 11/12/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 11/03/2021 07:00
Onsite Hours : 00:30

ASEC Report ID : 34339
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather :
Departure Time : 11/03/2021 07:30
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals.

A slab inspection for Lot #25 at Winslow was conducted for the preparation of concrete placement. No DCPs were completed as the slab had all wire & saddles placed and was covered with vapor barrier and stone.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.