

Date : 11/12/2021
Project No : 2020C007
Client Company : Pulte Group
Arrival Time : 10/11/2021 07:00
Onsite Hours : 02:00

ASEC Report ID : 34341
Name of the Project : Winslow at Brookstone
Project Location : 6156 Collins Road, Acworth, GA 30101
Weather : sunny / 61 degrees
Departure Time : 10/11/2021 09:00
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals.

The footing for Lot # 25 for Winslow @ Brookstone was inspected in preparation for concrete placement. A visual inspection, as well as a DCP test was conducted. The footing for Lot #25 appeared suitable for concrete placement. Please find the attached DCP report.

DCP TEST DATA SHEET

Project Name: Winslow
Project Number: 2020C007
Project Location: Lot #25
Date: 10/11/21
Technician: Russ Hendrix

DCP LOCATION:
Lot #,
North/South/Center
etc

#25 Footing

DCP LOCATION:
Lot #,
North/South/Center
etc

Depth (feet)	Set 2"	N 1.75"	Description
1		14	Red fine Sandy silt
2		10	Red fine Sandy silt
3		8	Grey Silty fine sand
4		7	Grey Silty fine sand
5		8	Red Silty Clay
6		9	Red Silty Clay
7			
8			
9			
10			

Depth (feet)	Set 2"	N 1.75"	Description
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.