

Date : 10/30/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 10/30/2021 12:00
Onsite Hours : 01:30

ASEC Report ID : 34384
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 10/30/2021 13:30
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

- Continued the excavation and pipe laying in the area of lot 293 and the surrounding cul-de-sac area.
- Placement of structural fill has been halted at the current time of this visit due to site conditions being too wet from rain on previous days.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.