

Date : 11/01/2021
Project No : 2021C073
Client Company : DR Horton West
Arrival Time : 11/01/2021 13:30
Onsite Hours : 02:30

ASEC Report ID : 34418
Name of the Project : Tributary C2A
Project Location : Riverside Parkway, City of Douglasville, GA
Weather : Partly Cloudy
Departure Time : 11/01/2021 16:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following were observations that were made at this time: Placement of 18" concrete drain pipe for street drains on backstreet between Lots #418 through 429. No density tests were done due to nothing being ready for testing.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.