

Date : 11/20/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 11/20/2021 06:00
Onsite Hours : 11:00

ASEC Report ID : 34563
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Sunny
Departure Time : 11/20/2021 17:00
ASEC Technician Name : Dave Bek

Test Date	Test Number	Moisture Content (%)	Dry Density (pcf)	Proctor Number	Max. Dry Density (pcf)	Optimum Moisture (%)	Compaction (%)	Specified Compaction (%)	ASTM Test Method	Pass/Fail
11/20/2021	1	18.9	103.9	P-3	103.0	18.1	100.9	95	D6938	Pass
Location : Lot number 252, Elv/Depth :825										
Comment :										
Tested By : Ramchandra Mogulla Gauge Serial No. : 54654										

Remark: Test performed in general accordance with signed referenced ASTM Method.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

ASEC Report ID : 34563
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Sunny
Departure Time : 11/20/2021 17:00
ASEC Technician Name : Dave Bek

Date : 11/20/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 11/20/2021 06:00
Onsite Hours : 11:00

PROCTOR DATA SUMMARY

TEST DATE	PROCTOR ID	MAX DRY DENSITY (pcf)	OPTIMUM MOISTURE (%)	PROCTOR TYPE	SOIL DESCRIPTION
08/01/2021	P-1	85.8	31.0	Standard	Light brown Silty CLAY
08/01/2021	P-2	111.3	14.6	Standard	Light brown Silty SAND
08/01/2021	P-3	103.0	18.1	Standard	Light brown Silty SAND