

Date : 07/07/2021
Project No : 2021C058
Client Company : Pulte Group
Arrival Time : 07/07/2021 08:00
Onsite Hours : 02:00

ASEC Report ID : 34627
Name of the Project : Parkside at Mason Mill
Project Location : Decatur, GA
Weather : sunny
Departure Time : 07/07/2021 10:
ASEC Technician Name : Andrew McCullough

As requested, an ASEC technician was present at the above referenced site for the purpose of conducting a basement wall inspection for lots #213-217

The wall evaluation was inspected visually for rebar type, spacing and lap distance.

The wall preparations appear to be in accordance with Southeast Zone, Date 12/08/2015, Carver & Eddington, NPC plan Number 2468.238-2468.237, Pulti Structural Drawling and appears to be ready for concrete placement.

The superintendent has been notified of these findings.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.