

Date : 01/20/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/12/2022 07:30
Onsite Hours : 01:30

ASEC Report ID : 52946
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 27, cold
Departure Time : 01/12/2022 09:00
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

Upon arrive at Lot #73 it was noted that the rebar and forms were not completed on the south side of the home location. A discussion was held with the foreman of the footing crew. It was requested that upon completion pictures would be sent of the deficient area. These pictures were received later and our representative re-inspected.

Our inspection found rebar met job specification for size, quantity, and spacing. The footing probed firm using a 3/8" diameter probe rod. A DCP test was conducted at the road frontage. Please find the attached table for our results.

DCP TEST DATA SHEET

Project Name: Suncity **Date:** 01/20/22
Project Number: 2021c060 **Technician:** Russell Hendrix
Project Location: Griffin, GA

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Lot 73 expedition,
Northeast at
roadfront

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		7	Red fine sandy silt	1			
2		11	Red fine sandy silt	2			
3		11	Red fine sandy silt	3			
4		13	Light brown fine sandy silt	4			

Date : 01/20/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/12/2022 07:30
Onsite Hours : 01:30

ASEC Report ID : 52946
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 27, cold
Departure Time : 01/12/2022 09:00
ASEC Technician Name : Russell Hendrix

5	5
6	6
7	7
8	8
9	9
10	10

DCP LOCATION:
Lot #,
North/South/Cente
r etc

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1				1			
2				2			
3				3			
4				4			
5				5			
6				6			
7				7			
8				8			
9				9			
10				10			

NOTES:

Date : 01/20/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/12/2022 07:30
Onsite Hours : 01:30

Daily Field Report

ASEC Report ID : 52946
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 27, cold
Departure Time : 01/12/2022 09:00
ASEC Technician Name : Russell Hendrix



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.