

Date : 02/03/2022
 Project No : 2021C060
 Client Company : Pulte Group
 Arrival Time : 01/18/2022 13:00
 Onsite Hours : 01:00

ASEC Report ID : 53026
 Name of the Project : Suncity - Peachtree
 Project Location : Griffin, GA
 Weather : 43
 Departure Time : 01/18/2022 14:00
 ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

Upon arrival, for Lot #38 Pod 17 it was observed that all rebar was placed as per job specifications for size, spacing, and quantity. The previous days freezing rain caused accumulation of two (2) inches of muck in the bottom of the footing. Our representative recommended demucking the footing to remove deleterious materials. Dynamic Cone Penetrometer Testing (DCP) were performed. Footings were found to have a soil bearing pressure of 2,500 psf. Please see the attached table.

DCP TEST DATA SHEET

Project Name: suncity **Date:** 01/18/22
Project Number: 2021c060 **Technician:** Russ Hendrix
Project Location: Griffin, GA

DCP LOCATION:
Lot #, Lot 38 Pod 17,
North/South/Cente Southeast footing
r etc

DCP LOCATION:
Lot #, Lot 38 offset
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1		10	Red fine sandy silt	1			Red fine sandy silt
2		16	Red fine sandy silt	2		AR	Red fine sandy silt
3		ar		3			
4				4			
5				5			
6				6			
7				7			

Date : 02/03/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/18/2022 13:00
Onsite Hours : 01:00

ASEC Report ID : 53026
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 43
Departure Time : 01/18/2022 14:00
ASEC Technician Name : Russell Hendrix

8	8
9	9
10	10

DCP LOCATION:
Lot #,
North/South/Cente
r etc

DCP LOCATION:
Lot #,
North/South/Cente
r etc

Depth (feet)	Set 2"	N 1.75"	Description	Depth (feet)	Set 2"	N 1.75"	Description
1				1			
2				2			
3				3			
4				4			
5				5			
6				6			
7				7			
8				8			
9				9			
10				10			

NOTES:


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without

Date : 02/03/2022
Project No : 2021C060
Client Company : Pulte Group
Arrival Time : 01/18/2022 13:00
Onsite Hours : 01:00

Daily Field Report

ASEC Report ID : 53026
Name of the Project : Suncity - Peachtree
Project Location : Griffin, GA
Weather : 43
Departure Time : 01/18/2022 14:00
ASEC Technician Name : Russell Hendrix

written approval from AS Engineering and Consulting LLC.