

Date : 02/24/2022
Project No : 2021C058
Client Company : Pulte Group
Arrival Time : 02/05/2022
Onsite Hours :

ASEC Report ID : 53174
Name of the Project : Parkside at Mason Mill
Project Location : Decatur, GA
Weather : 50 / rain
Departure Time : 02/05/2022
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

A request was made for a visual footing and reinforcing steel inspection for Lots #125 through #131. The technician arrived and found that rebar placement and wall footing forming were not completed.


Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.