

Date : 08/26/2021
Project No : 2021C073
Client Company : DR Horton West
Arrival Time : 08/26/2021 08:00
Onsite Hours : 02:00

ASEC Report ID : 33791
Name of the Project : Tributary C2A
Project Location : Riverside Parkway, City of Douglasville, GA
Weather : Artsy cloudy
Departure Time : 08/26/2021 10:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

- Work being done to clean up the site and turn soil to dry out soil for future use.
- Due to the amount of rainfall the night before the site was too wet for fill placement today.



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.