

Date : 08/03/2021
Project No : 2021C074
Client Company : DR Horton West
Arrival Time : 08/03/2021 10:00
Onsite Hours : 03:00

ASEC Report ID : 33861
Name of the Project : Oakhurst Glen - Ph 4
Project Location : Mallord Drive, South Fulton, GA
Weather : Partly cloudy
Departure Time : 08/03/2021 13:00
ASEC Technician Name : Christopher Burrow II

The undersigned ASEC Inspector was on site, on the above date, for the purpose of general site monitoring and assessment of contractor and subcontractor activities. The following are observations that were made at this time:

Concrete was tested on this date as it was poured into the forms for the retaining wall surrounding the retention pond. Below listed are the results of these tests.

Truck 1, 10 yds

Truck 5, 50 yds.

Temperature: 87 degrees

Temperature: 88 degrees

Slump: 6 inches

Slump: 5.5 inches

Air content: 4.2

Air content: 4.1

Unit Weight: 144 lbs

Unit Weight: 145.1 lbs.

Ambient temperature: 77 degrees.

Ambient Temperature: 78 degrees



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.