

Date : 03/31/2022
Project No : 2021C073
Client Company : DR Horton West
Arrival Time : 03/10/2022
Onsite Hours :

ASEC Report ID : 53441
Name of the Project : Tributary C2A
Project Location : Riverside Parkway, City of Douglasville, GA
Weather : 55 sunny
Departure Time : 03/10/2022
ASEC Technician Name : Russell Hendrix

The site was visited by the undersigned AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to assure compliance with project drawings/specifications, applicable codes, and materials submittals. The following observations were made on site today:

Upon arrival to the site no work was being completed due to soil high moisture levels.



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.