

Date : 02/03/2023
Project No : 2022C235
Client Company : Jackson Demolition Service, Inc.
Arrival Time : 02/03/2023 06:00
Onsite Hours : 10:30

ASEC Report ID : 56485
Name of the Project : Plant Gorgas Demolition and Grading
Project Location : 460 Gorgas Rd, Parrish, AL 35580
Weather : Sunny
Departure Time : 02/03/2023 16:30
ASEC Technician Name : Vidal Dias

AS ENGINEERING AND CONSULTING, LLC (ASEC) representative Vidal Dias visited the site at the request of Jackson Demolition representative Josh Kelly. The undersigned representative was present to monitor, test and document the ongoing project activities.

During the visit, following observations were made:

1. The contractor installed geogrid over the previously placed crushed concrete layer.
2. The geogrid was verified to be TerraGrid RX1100.
3. Geogrid was installed in unit 10 of the basement floor.
4. Twenty-two rolls of TerraGrid were placed in areas G7 and G8 and forty feet into H7 and H8 in accordance with the project drawings. (Drawing# E720667).
5. The undersigned representative verified overlap lengths and side wall coverage.

Please let us know if you have any questions regarding our observations or this transmittal. We will be more than glad discuss our findings.



Geogrid installation verified for overlap



Geogrid installation verified for overlap



Geogrid installation verified for side wall coverage



Geogrid installation verified for side wall coverage



Ramchandra R. Mogulla
GA P.E. 036021
Senior Engineer

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.