

Date : 06/16/2026  
Project No : 2025C216  
Client Company : Artisan  
Arrival Time : 06/16/2026 08:00  
Onsite Hours : 07:00

ASEC Report ID : 95432  
Name of the Project : NW (Lots) Unit 4 PH 1A & 1B  
Project Location : Dallas  
Weather : Overcast  
Departure Time : 06/16/2026 15:00  
ASEC Technician Name : Sean Willett

| Test Date                                                             | Test Number | Moisture Content (%) | Dry Density (pcf) | Proctor Number | Max. Dry Density (pcf) | Optimum Moisture (%) | Compaction (%) | Specified Compaction (%) | ASTM Test Method | Pass/Fail |
|-----------------------------------------------------------------------|-------------|----------------------|-------------------|----------------|------------------------|----------------------|----------------|--------------------------|------------------|-----------|
| 06/16/2026                                                            | 1           | 29.3                 | 83.8              | 2025-032 SP    | 94.9                   | 25.0                 | 88.3           | 95                       | D6938            | Fail      |
| Location : 4900-5000 roadway, Elv/Depth : 7 feet below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                             |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett Gauge Serial No. : 77-19952                  |             |                      |                   |                |                        |                      |                |                          |                  |           |
| 06/16/2026                                                            | 2           | 28.0                 | 88.1              | 2025-032 SP    | 94.9                   | 25.0                 | 92.8           | 95                       | D6938            | Fail      |
| Location : 4900-5000 roadway, Elv/Depth : 7 feet below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                             |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett Gauge Serial No. : 77-19952                  |             |                      |                   |                |                        |                      |                |                          |                  |           |
| 06/16/2026                                                            | 3           | 27.2                 | 87.6              | 2025-032 SP    | 94.9                   | 25.0                 | 92.3           | 95                       | D6938            | Fail      |
| Location : 4900-5000 roadway, Elv/Depth : 7 feet below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                             |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett Gauge Serial No. : 77-19952                  |             |                      |                   |                |                        |                      |                |                          |                  |           |
| 06/16/2026                                                            | 4 retest    | 22.9                 | 96.6              | 2025-032 SP    | 94.9                   | 25.0                 | 101.8          | 95                       | D6938            | Pass      |
| Location : 4900-5000 roadway, Elv/Depth : 7 feet below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                             |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett Gauge Serial No. : 77-19952                  |             |                      |                   |                |                        |                      |                |                          |                  |           |
| 06/16/2026                                                            | 5 retest    | 24.5                 | 91.6              | 2025-032 SP    | 94.9                   | 25.0                 | 96.5           | 95                       | D6938            | Pass      |
| Location : 4900-5000 roadway, Elv/Depth : 7 feet below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                             |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett Gauge Serial No. : 77-19952                  |             |                      |                   |                |                        |                      |                |                          |                  |           |
| 06/16/2026                                                            | 6 retest    | 26.7                 | 83.9              | 2025-032 SP    | 94.9                   | 25.0                 | 88.4           | 95                       | D6938            | Fail      |
| Location : 4900-5000 roadway, Elv/Depth : 7 feet below finished grade |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Comment :                                                             |             |                      |                   |                |                        |                      |                |                          |                  |           |
| Tested By : Sean Willett Gauge Serial No. : 77-19952                  |             |                      |                   |                |                        |                      |                |                          |                  |           |

**Remark:** Test performed in general accordance with signed referenced ASTM Method.



**Kenneth Mosman**

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.

Date : 06/16/2026  
Project No : 2025C216  
Client Company : Artisan  
Arrival Time : 06/16/2026 08:00  
Onsite Hours : 07:00

ASEC Report ID : 95432  
Name of the Project : NW (Lots) Unit 4 PH 1A & 1B  
Project Location : Dallas  
Weather : Overcast  
Departure Time : 06/16/2026 15:00  
ASEC Technician Name : Sean Willett

---

**PROCTOR DATA SUMMARY**

| TEST DATE  | PROCTOR ID       | MAX DRY DENSITY<br>(pcf) | OPTIMUM<br>MOISTURE (%) | PROCTOR TYPE | SOIL DESCRIPTION                |
|------------|------------------|--------------------------|-------------------------|--------------|---------------------------------|
| 07/28/2025 | 2025-031 SP      | 101.0                    | 20.7                    | Standard     | Tan, brown micaceous sandy silt |
| 07/28/2025 | 2025-032 SP      | 94.9                     | 25.0                    | Standard     | Red micaceous sandy clay        |
| 08/01/2025 | 2025-033 SP      | 104.0                    | 16.2                    | Standard     | Tan, brown micaceous sandy silt |
| 08/14/2025 | 2025-035 SP      | 107.8                    | 13.0                    | Standard     | Red sandy silt                  |
| 08/14/2025 | 2025-036 SP      | 107.0                    | 18.5                    | Standard     | Red micaceous sandy silt        |
| 01/30/2026 | Field proctor #6 | 98.0                     | 17.2                    | Standard     | Multi-colored sandy SILT        |