

Date : 06/18/2026
Project No : 2026C101
Client Company : Artisan
Arrival Time : 06/18/2026 08:00
Onsite Hours : 04:00

ASEC Report ID : 95430
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots
Project Location : Dallas
Weather : Overcast
Departure Time : 06/18/2026 12:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site to observe the contractor and for the observation/testing of the placement of fill/backfill. The pipe crew continued the installation of storm line D-7 to D-8. ASEC performed density testing and provided test results to the contractor. During the installation, a rainstorm hit the site. It was raining hard enough that the contractors needed to shut down for the rest of the day. ASEC left the site.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 06/18/2026
Project No : 2026C101
Client Company : Artisan
Arrival Time : 06/18/2026 08:00
Onsite Hours : 04:00

ASEC Report ID : 95430
Name of the Project : Seven Hills PHASE 13, UNIT 4 Lots
Project Location : Dallas
Weather : Overcast
Departure Time : 06/18/2026 12:00
ASEC Technician Name : Sean Willett



Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.