

Date : 06/22/2026
Project No : 2026C125
Client Company : Lewis Contracting
Arrival Time : 06/22/2026 12:00
Onsite Hours : -5:30

ASEC Report ID : 95988
Name of the Project : Pittman Park - Garibaldi St. Stormwater
Project Location : Atlanta
Weather : clear and sunny
Departure Time : 06/22/2026 7:30
ASEC Technician Name : Narayana Ganesh Undavalli

Location(S):

Testing: 2 Set of concrete specimens (6 per set) were cast during the cast-in-place concrete pour at the above referenced location, in accordance with ASTM C31. The specimen will remain on site for the initial 24-48 hrs curing.

Compliance: ☒ Field placement of concrete appeared to be in general accordance with the project specifications (i.e., slump, temperature, etc) (refer to remarks below)
☐ Deviations and/or noncompliances were noted during the field placement (refer to remarks below)

Specimen Pick Up: 2 Sets of concrete specimens/ 6 specimen per set were picked up & transported to AS Engineering and Consulting LLC (ASEC) for curing and testing in accordance with ASTM C39, C670/1231

Field Curing: Specimen were stored for the initial 24 hours
☒ Near the poured structure
☐ In an insulated curing box
☐ Other

Remarks: Test 1 Temp of concrete = 85 amb temp = 85 slump = 3.5 air = 0.75 unit wt of concrete = 142. Test 2 Temp of concrete = 90 amb temp = 85 slump = 5 air = 1.5 unit wt of concrete = 142. Test 3 Temp of concrete = 90 amb temp = 75 Slump = 4 air = 1.5 unit wt of concrete = 143.

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.