

Date : 07/06/2026
Project No : 2026C125
Client Company : Lewis Contracting
Arrival Time : 07/06/2026 12:00
Onsite Hours : 05:00

ASEC Report ID : 96126
Name of the Project : Pittman Park - Garibaldi St. Stormwater
Project Location : Atlanta
Weather : Sunny
Departure Time : 07/06/2026 17:00
ASEC Technician Name : Sean Willett

As requested, the site was visited by our AS Engineering and Consulting (ASEC) representative for the purpose of providing quality control inspection and testing services. Visual observation techniques were employed to verify compliance with project drawing/specifications, applicable codes, and materials submittals. The following observations were observed on site this day.

Our ASEC representative was on site as requested by the contractor for the observation/testing of the placement of concrete. The contractors poured concrete in the walls A, C, and D for the concrete retaining wall located at the entrance of the site. A set of cylinders and testing was conducted within every 25 yards as requested by the site specifications. Test results were provided to the contractor. Cylinders were stored on site and will be transported to the lab on the following day.

We appreciate the opportunity to be of service to you on this project. If you have any questions regarding this report, please feel free to contact us. We will be more than happy to discuss it with you.



Date : 07/06/2026
Project No : 2026C125
Client Company : Lewis Contracting
Arrival Time : 07/06/2026 12:00
Onsite Hours : 05:00

ASEC Report ID : 96126
Name of the Project : Pittman Park - Garibaldi St. Stormwater
Project Location : Atlanta
Weather : Sunny
Departure Time : 07/06/2026 17:00
ASEC Technician Name : Sean Willett



The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.