

Date : 09/03/2026
Project No : Admin
Client Company : ASEC
Arrival Time : 09/03/2026 09:00
Onsite Hours : 02:30

ASEC Report ID : 97418
Name of the Project : Administrative - Non Billable
Project Location : N/A
Weather : Sunny
Departure Time : 09/03/2026 11:30
ASEC Technician Name : Clyde Smith

On the above date the writer was on site as requested at 145 Rosemary Landing project #887082 for inspection at footings/slab. The footings were observed by probing the bottoms using a rounded end steel rod at intervals of two to three feet. The in place fill and residual soils appeared suitable for a design bearing pressure of 3000 psf. The writer also observed reinforcing at continuous wall footings and floor slab reinforcing (2 # 4 continuous bars in place at all required locations. Lot number ,1074 NatureWalk @Seven Hills



Continuous exterior wall footings



Floor slab footings



Continuous reinforcing steel in place

Date : 09/03/2026
Project No : Admin
Client Company : ASEC
Arrival Time : 09/03/2026 09:00
Onsite Hours : 02:30

ASEC Report ID : 97418
Name of the Project : Administrative - Non Billable
Project Location : N/A
Weather : Sunny
Departure Time : 09/03/2026 11:30
ASEC Technician Name : Clyde Smith



Building permit



Probing bottom of footings



Kenneth Mosman

Kenneth Mosman

The results presented in this report relate only to the items tested. This report shall not be reproduced, except in full, without written approval from AS Engineering and Consulting LLC.